

ORIGINAL ARTICLE

Examination of endoscopic intracanal observation with an ultrafine-diameter scope

Takeshi Jinno¹  | Kazuya Miyaguchi²  | Daiki Muraishi¹ | Toshiyuki Narumi¹ | Kanji Kabasawa¹ | Hideki Ohgo² | Yoshikazu Tsuzuki² | Hiroyuki Imaeda²

¹Department of Clinical Engineering, Saitama Medical University, Saitama, Japan

²Department of Gastroenterology, Saitama Medical University, Saitama, Japan

Correspondence

Hiroyuki Imaeda, Department of Gastroenterology, Saitama Medical University, 38 Morohongo, Moroyamamachi, Iruma-gun, Saitama 350-0495, Japan.
Email: imaedahi@yahoo.co.jp

Funding information

None

Abstract

Objectives: The endoscopic channel can be damaged by instruments during use and cleaning, leading to contamination, infection, and increased repair costs. However, few devices are available to observe the inside of the endoscopic channel. This study employed an ultrafine-diameter scope to examine damage in the endoscopic channel.

Methods: Fifty-eight endoscopes used at our institution were examined for scratches, discoloration, or deformation in the endoscopic channel using an ultrafine-diameter scope.

Results: Damage was observed in seven of the 24 observation endoscopes and 27 of the 34 therapeutic endoscopes, with damage being more common in the therapeutic endoscopes. Scratches were observed in nine of the 25 upper gastrointestinal endoscopes, 23 of the 24 colonoscopes, and one of the two echoendoscopes. Additionally, two colonoscopes, one echoendoscope, and one double-balloon endoscope showed indentation or narrowing near the curvature.

Conclusions: The use of an ultrafine-diameter scope enabled the detection of minute damage and deformations in the channel. Periodic observation with the ultrafine-diameter scope may promote the long-term use of the scopes.

KEYWORDS

endoscope inspection, endoscopic intracanal injury, EYEBOSCO, SDGs, ultrafine scope

INTRODUCTION

The inside of the endoscopic channel can be damaged during use or by cleaning tools. Such damage can lead to issues, including contamination, infection, and costly repairs due to scope malfunction, as well as difficulties in cleaning and disinfection caused by the complicated scope structure.¹ European guidelines recommend that endoscopes be disinfected immediately before the first patient examination of the day and during periodic bacterial tests of gastrointestinal endoscopic equipment.² Infections following gastrointestinal endoscopy are most

frequently caused by the patient's endogenous intestinal microbiota.

A systematic review of 117 articles revealed that the composite infection rate was 0.2% following gastrointestinal endoscopic procedures, 0.8% following endoscopic retrograde cholangiopancreatography (ERCP), 0.123% following non-ERCP upper gastrointestinal endoscopic procedures, and 0.073% following lower gastrointestinal endoscopic procedures.³

In Japan, periodic culture tests and other cleanliness assessments are considered desirable to ensure the hygienic quality of endoscopic devices. However, no

This is an open access article under the terms of the [Creative Commons Attribution](https://creativecommons.org/licenses/by/4.0/) License, which permits use, distribution and reproduction in any medium, provided the original work is properly cited.

© 2025 The Author(s). *DEN Open* published by John Wiley & Sons Australia, Ltd on behalf of Japan Gastroenterological Endoscopy Society.



FIGURE 1 Appearance of EYEBOSCO.

reports exist on devices specifically designed to observe the inside of the channels. Recently, green endoscopy has gained prominence for its potential to reduce waste, conserve water and energy resources, and minimize unnecessary endoscopic examinations.⁴

Treating endoscopes with care is crucial, and this includes performing periodic endoscope inspections. In this report, we discuss our observations of the inside of an endoscopic channel using the EYEBOSCO (ABIS Inc, Hyogo, Japan), an ultrafine-diameter scope.

METHODS

Study design

The EYEBOSCO was inserted through the suction cylinder of the endoscope for observation and video recording (Figure 1). The internal structure of the endoscope is shown in Figure 2. EYEBOSCO is a reusable product and requires cleanliness treatment after use. Therefore, it was disinfected with an alcohol cleaning cloth following the observation. The endoscope was also disinfected using EYEBOSCO after high-level disinfection and again after use. The observation paths were as follows: from the suction cylinder to the forceps port at the end of the scope and from the suction cylinder to the suction port. The video recordings were examined for any flaws, discoloration, and channel deformation.

Definition of injuries

In contrast to the normal state (Figure 3), scratches were defined as scrape-like marks, discoloration as clear color changes, and deformation as narrowing of the image. The survey results were compared with the target scope (Figure 4; Figure 5–7).

Scope

The study used the EYEBOSCO inspection scope as the ultrafine-diameter scope. The EYEBOSCO has an outer diameter of 2.0 mm, a length of 1.95 m, and is flexible and soft, making it ideal for observing the inside of a digestive endoscopic channel. This device facilitates observation inside the channel of a gastrointestinal endoscope.

The target endoscopes included upper gastrointestinal endoscopes (GIF-H290: 5; GIF-H290Z: 4; GIF-Q260J: 3; GIF-XZ1200: 2; GIF-XP290N: 2; GIF-H290EC: 1; EG-580NW: 2; EG-L590WR: 2; EG-L600ZW: 2; EG-L600ZW7: 2; Total: 25), colonoscopes (CF-H260AI: 1; CF-H290ECI: 1; CF-H290I: 1; CF-HQ290I: 1; CF-Q260AI: 2; CF-Q260DI: 1; CF-XZ1200I: 1; PCF-PQ260L: 1; PCF-Q260AZI: 1; PCF-Q260JI: 1; PCF-Q260AI: 2; PCF-H290TI: 1; PCF-H290ZI: 2; PCF-H290DI: 2; EC-L600ZP: 4; EC-L600ZP7: 1; EC-L600XP7/L: 1; Total: 24), duodenoscopes (JF-260V: 2; TJF-260V: 1; Total: 3), echoendoscopes (GF-UCT260: 1; GF-UE260-AL5: 1; EG-740UT: 1; Total: 3), and double balloon endoscopes (EI-580BT: 1; EN-580T: 1; EN-580XP: 1; Total: 3) manufactured by Olympus and Fujifilm, with forceps channels ranging from 2.0 to 4.2 mm. They were categorized into observation and therapeutic endoscopes according to their specified use (Table 1).

Outcome measurements

The primary endpoints were the number of injuries in the observation and therapeutic endoscopes. The secondary endpoints were the type and number of injuries classified based on injury type and endoscope category.

Statistical analyses

Categorical variables were compared between groups using Pearson's χ^2 test. All statistical analyses were performed using IBM SPSS Statistics for Windows, version 26 (IBM Corp.). Statistical significance was considered at $p < 0.05$, and all tests were two-sided.

RESULTS

We surveyed 24 and 34 observation and therapeutic endoscopes, respectively, used at the Saitama Medical University Hospital. The observation set included 22 upper gastrointestinal endoscopes, one echoendoscope, and one double-balloon endoscope. The procedure set included two upper gastrointestinal scopes, 24 colonoscopes, three duodenoscopes, two echoendoscopes, and two double-balloon endoscopes (Table 1).




FIGURE 2 Lumen structure of the scope (blue arrows indicate areas observed in this study). Retrieved and modified from <https://abdominalkey.com/2-endoscopic-equipment>.



FIGURE 3 Actual observation of the lumen of an endoscope using EYEBOSCO.

Overall, seven (29.2%) and 27 (79.4%) observation and therapeutic endoscopes, respectively, had scratches, discolorations, or deformations; injuries were more common in the therapeutic endoscopes (p -value = 0.00006).




FIGURE 4 Normal image of the endoscopic channel.

Six (25%) and 27 (79.4%) observation and therapeutic endoscopes, respectively, had scratches in the channel ($p = 0.00001$), indicating that the number of scratched therapeutic endoscopes was significantly higher than that of observation endoscopes.

Discoloration was found in two (8.3%) and 10 (29.4%) observation and therapeutic endoscopes, respectively ($p = 0.052$). One observation endoscope (4.2%) and two therapeutic endoscopes (5.9%) showed deformations in the channel ($p = 0.776$; Table 2).

The presence of damage (scratches, discoloration, and deformation) was also examined according to scope



FIGURE 5 Scratches in the endoscopic channel (indicated by red arrows).




FIGURE 7 Narrowing in the endoscopic channel.




FIGURE 6 Discoloration in the endoscopic channel.

type. Among the 22 upper gastrointestinal scopes used for observation, six (16.7%) were found to be damaged. Three upper gastrointestinal scopes (100%) used for treatment were found to be damaged. Additionally, 23 (95.8%) of the 24 colonoscopes were damaged.

The observation echoendoscope was not damaged, although its therapeutic equivalent was damaged. The double-balloon endoscope used for observation was damaged in one case.

Neither of the double-balloon endoscopes used for treatment were damaged (Table 3).

DISCUSSION

Observation of the endoscopic channel and early detection of tract damage or discoloration may help prevent endoscopically transmitted infections. Among the various possible injuries to endoscopes, wounds are particularly problematic because bacteria can settle in them and cause infections. The endoscopic channel is easily damaged by the passage of forceps and other instruments. If organic matter adheres to the damaged area, we speculate that disinfection may be ineffective because its removal is difficult with standard cleaning methods. An Egyptian study showed that the reuse of biopsy forceps during colonoscopy increases the risk of Hepatitis C virus infection in patients.⁶

Damage to the scope after the procedure, particularly from scratches, may lead to an increase in bacterial growth. Composite infection rates have been reported at 0.2% after gastrointestinal endoscopic procedures, 0.8% after ERCP, 0.123% after non-ERCP upper gastrointestinal endoscopic procedures, and 0.073% after lower gastrointestinal endoscopic procedures. *Pseudomonas aeruginosa* was the most prevalent organism, followed by other *Enterobacteriaceae* spp. and Gram-positive cocci.³ Additionally, Pajkos et al. have previously confirmed biofilm formation in the endoscopic tract and reported that biofilm may contribute to endoscopic contamination.⁵

TABLE 1 Target endoscopes.

Aim		Observation, N = 24		Therapeutic, N = 34		p-value
Company		O	F	O	F	
Upper gastrointestinal endoscope		14	8	3	0	0.527
Colonoscope		0	0	18	6	—
Duodenoscope		0	0	3	0	—
Echoendoscope		1	0	1	1	1.0
Double-balloon endoscope		0	1	0	2	—
Total		15	9	25	9	0.402

Upper gastrointestinal endoscope	Company	Aim	Forceps channels ranging	From the date of purchase to test and inspection (months)	Time from last repair date to test inspection (months)
GIF-H290	O	Observation use	2.8	55	7
GIF-H290	O	Observation use	2.8	55	2
GIF-H290	O	Observation use	2.8	7	No records of repair
GIF-H290	O	Observation use	2.8	55	24
GIF-H290	O	Observation use	2.8	55	36
GIF-H290EC	O	Observation use	2.2	55	No records of repair
GIF-H290Z	O	Observation use	2.8	79	26
GIF-H290Z	O	Observation use	2.8	79	17
GIF-H290Z	O	Observation use	2.8	76	No records of repair
GIF-H290Z	O	Observation use	2.8	55	11
GIF-Q260J	O	Treatment use	3.2	51	No records of repair
GIF-Q260J	O	Treatment use	3.2	51	19
GIF-Q260J	O	Treatment use	3.2	51	0
GIF-XP290N	O	Observation use	2.2	51	7
GIF-XP290N	O	Observation use	2.2	55	4
GIF-XZ1200	O	Observation use	2.8	7	No records of repair
GIF-XZ1200	O	Observation use	2.8	7	No records of repair
EG-L580NW	F	Observation use	2.4	79	5
EG-L580NW	F	Observation use	2.4	79	3
EG-L590WR	F	Observation use	2.8	79	10
EG-L590WR	F	Observation use	2.8	79	2
EG-L600ZW	F	Observation use	2.8	79	13
EG-L600ZW	F	Observation use	2.8	79	9
EG-L600ZW7	F	Observation use	2.8	34	3
EG-L600ZW7	F	Observation use	2.8	11	1

Colonoscope	Company	Aim	forceps channels ranging	From the date of purchase to test and inspection (months)	Time from last repair date to test inspection (months)
CF-H260AI	O	Treatment use	3.7	127	No records of repair
CF-H290ECI	O	Treatment use	3.2	55	No records of repair
CF-H290I	O	Treatment use	3.2	55	36
CF-HQ290I	O	Treatment use	3.7	114	30
CF-Q260AI	O	Treatment use	3.2	234	25
CF-Q260AI	O	Treatment use	3.2	234	8

(Continues)

TABLE 1 (Continued)

Colonoscope	Company	Aim	forceps channels ranging	From the date of purchase to test and inspection (months)	Time from last repair date to test inspection (months)
CF-Q260DI	O	Treatment use	3.2	112	49
CF-XZ1200I	O	Treatment use	3.7	6	No records of repair
PCF-H290DI	O	Treatment use	3.2	3	No records of repair
PCF-H290DI	O	Treatment use	3.2	7	No records of repair
PCF-H290TI	O	Treatment use	3.2	51	No records of repair
PCF-H290ZI	O	Treatment use	3.2	55	No records of repair
PCF-H290ZI	O	Treatment use	3.2	55	13
PCF-PQ260L	O	Treatment use	2.8	79	11
PCF-Q260AI	O	Treatment use	3.2	210	21
PCF-Q260AI	O	Treatment use	3.2	234	3
PCF-Q260AZI	O	Treatment use	3.2	127	No records of repair
PCF-Q260JI	O	Treatment use	3.2	79	No records of repair
EC-L600XP7/L	F	Treatment use	2.8	11	No records of repair
EC-L600ZP	F	Treatment use	3.2	79	10
EC-L600ZP	F	Treatment use	3.2	79	9
EC-L600ZP	F	Treatment use	3.2	79	9
EC-L600ZP	F	Treatment use	3.2	79	9
EC-L600ZP7	F	Treatment use	3.2	58	12
Duodenoscope	Company	Aim	Forceps channels ranging	From the date of purchase to test and inspection (months)	Time from last repair date to test inspection (months)
JF-260V	O	Treatment use	3.7	199	0
JF-260V	O	Treatment use	3.7	55	3
TJF-260V	O	Treatment use	4.2	76	No records of repair
Echoendoscope	Company	Aim	Forceps channels ranging	From the date of purchase to test and inspection (months)	Time from last repair date to test inspection (months)
GF-UCT260	O	Treatment use	3.7	101	1
GF-UE260-AL5	O	Observation use	2.2	55	No records of repair
EG-740UT	F	Treatment use	4.0	1	No records of repair
Double-balloon endoscope	Company	Aim	Forceps channels ranging	From the date of purchase to test and inspection (months)	Time from last repair date to test inspection (months)
EI-580BT	F	Treatment use	3.2	79	16
EN-580T	F	Treatment use	3.2	79	15
EN-580XP	F	Observation use	2.2	76	10

Abbreviations: F, Fujifilm; O, Olympus.

In this study, we anticipated that duodenoscopes, as well as upper and lower gastrointestinal endoscopes used for treatment and observation, would show predominant differences in damage. Using the EYEBOSCO enabled us to observe the inside of the endoscope channels and identify flaws and deformities that could not previously be detected. We found that damage was primarily observed in the scopes used for procedures. Most injuries were found on colonoscopes and were believed to be caused by the injection needles used

for endoscopic mucosal resection and endoscopic sub-mucosal dissection. The cause of the discolorations remains unknown but may change over time. External energy from dropping the scope may have caused the deformations. This may explain why no significant differences were observed in discoloration and deformation between the endoscopes used for observation and treatment in this study.

Scopes with confirmed flaws and deformities were significantly more likely to be in use for procedures.

TABLE 2 Breakdown of endoscopes with confirmed scratches, discoloration, or deformation.

	Observation, N = 24	Therapeutic, N = 34	p-value
Total	7 (29.2%)	27 (79.4%)	0.00006
Scratches	6 (25%)	27 (79.4%)	0.00001
Discoloration	2 (8.3%)	10 (29.4%)	0.052
Deformation	1 (4.2%)	2 (5.9%)	0.776

TABLE 3 Comparison of scratches, discoloration, and deformation in endoscopic channels between observation and treatment use.

Aim	Observation, N = 24	Therapeutic, N = 34	p-value
Upper gastrointestinal endoscope	6 (16.7%)	3 (100%)	0.0182
Colonoscopy	0	23 (95.8%)	—
Duodenoscopy	0	0	—
Echoendoscopy	0	1 (50%)	—
Double-balloon endoscopy	1 (100%)	0	—
Total	7 (29.2%)	27 (79.4%)	0.00006

The use of instruments such as local injection needles for hemostasis and polyp/tumor resection may be responsible. Specifically, local injection needles can pass through the channel without being retracted into the sheath. Additionally, injury caused by rigid-tipped instruments, such as clip forceps or grasping forceps, may also be a factor. The difference in the extent of channel damage between the observation and therapeutic endoscopes—specifically, the therapeutic endoscope, which passes through the lumen more frequently—demonstrates that the damage is to some degree related to the repeated passage of the device during the procedure. Therefore, particular attention should be paid to handling before and after inserting instruments, as damage to the channel is possible, especially near the tip or curvature of the scope.

Disposable endoscopes have recently gained attention owing to their comparable visibility and diagnostic capabilities to those of conventional endoscopes. Garbin et al. developed and validated a disposable endoscope that costs \$357,⁷ whereas Bang et al. estimated that the break-even cost of disposable duodenoscopes is over \$1300 for low-volume centers (less than 50 ERCPs/year) and over \$800 for high-volume centers (more than 150 ERCP/year), depending on the infection rate.⁸ Conversely, conventional endoscopes are estimated to incur an additional expenditure of \$114 to \$280 per use for reprocessing, along with the high initial cost of acquisition.⁹

A recent study suggested that disposable colonoscopes offer larger cost savings in facilities with low colonoscopy use.¹⁰

Another issue with disposable endoscopes is their environmental impact. A recent study estimated the amount of non-recyclable waste generated if disposable gastrointestinal endoscopes were universally adopted in the US compared to reprocessed endoscopes. The study estimated that reprocessed endoscopes generate approximately 532,918 m³ of waste yearly in the US, while disposable duodenoscopes and colonoscopes would generate an additional 100,682 m³ of waste yearly.¹¹

Responding early to minute damage and deformation enables long-term scope use and promotes the efficient use of resources, in line with the Sustainable Development Goals. The EYEBOSCO facilitates the observation of endoscopic channels, allowing for the examination of instrument effects on the channel and their relationship to scope failure.

The limitations of this study include the small number of cases in this pilot study and the fact that treatment time was not considered for each endoscope. The impact of these findings on infection rates remains unclear, as infection rates were not examined. Similarly, the effect of these findings on scope repair needs was not examined. At the very least, the endoscope manufacturer does not set any restrictions on use based on the degree of endoscope damage. Damage to the inside of the channel can only be confirmed by identifying leaks, using a cleaning brush, or noting any discomfort when inserting forceps. Therefore, if there is an air leak or any abnormalities with the scope's insertion, its use must be discontinued. Future studies should include larger samples and assess the impact of these factors on infection rates and repair demands.

In conclusion, observing the inside of the endoscopic channel with an ultrafine-diameter scope enables the detection of microscopic damage and deformation. Periodic observation with an ultrafine-diameter scope may promote the long-term use of endoscopes.

ACKNOWLEDGMENTS

We would like to express our deep gratitude to Prof. Hidetomo Nakamoto for supporting this research.

CONFLICT OF INTEREST STATEMENT

None.

ETHICS STATEMENT

Ethical approval was not sought for the present study because this is not a study involving humans.

DATA AVAILABILITY STATEMENT

All the data used to support the findings of this study are included in this article.

ORCID

Takeshi Jinno 

<https://orcid.org/0009-0000-6689-2134>

Kazuya Miyaguchi 

<https://orcid.org/0000-0003-0701-3608>

REFERENCES

1. Spach DH, Silverstein FE, Stamm WE. Transmission of infection by gastrointestinal endoscopy and bronchoscopy. *Ann Intern Med* 1993; **118**: 117–282.
2. Beilenhoff U, Neumann CS, Rey JF *et al*. ESGE-ESGENA Guideline: Cleaning and disinfection in gastrointestinal endoscopy. *Endoscopy* 2008; **40**: 939–57.
3. Deb A, Perisetti A, Goyal H *et al*. Gastrointestinal endoscopy-associated infections: Update on an emerging issue. *Dig Dis Sci* 2022; **67**: 1718–32.
4. Rodríguez de Santiago E, Dinis-Ribeiro M, Pohl H *et al*. Reducing the environmental footprint of gastrointestinal endoscopy: European Society of Gastrointestinal Endoscopy (ESGE) and European Society of Gastroenterology and Endoscopy Nurses and Associates (ESGENA) Position Statement. *Endoscopy* 2022; **54**: 797–826.
5. Pajkos A, Vickery K, Cossart Y. Is biofilm accumulation on endoscope tubing a contributor to the failure of cleaning and decontamination? *J Hosp Infect* 2004; **58**: 224–9.
6. El-Demerdash T, Yousef M, Abd-Elsalam S, Helmy A, Kobtan A, Elfert AA. Reuse of biopsy forceps may be associated with risk of transmission of HCV in Egyptian patients undergoing gastrointestinal endoscopy. *Infect Disord Drug Targets* 2019; **19**: 279–83.
7. Garbin N, Mamunes AP, Sohn D, Hawkins RW, Valdastrì P, Obstein KL. Evaluation of a novel low-cost disposable endoscope for visual assessment of the esophagus and stomach in an ex-vivo phantom model. *Endosc Int Open* 2019; **7**: E1175–83.
8. Bang JY, Sutton B, Hawes R, Varadarajulu S. Concept of disposable duodenoscopy: At what cost? *Gut* 2019; **68**: 1915–7.
9. Ofstead CL, Quick MR, Eiland JE, Adams SJ. A glimpse at the true cost of reprocessing endoscopes: Results of a pilot project. *Communiqué* 2017: 63–78.
10. Larsen S, Kalloo A, Hutfless S. The hidden cost of colonoscopy including cost of reprocessing and infection rate: The implications for disposable colonoscopes. *Gut* 2020; **69**: 197–200.
11. Pohl H, von Renteln D. Environmental impact of disposable endoscopic equipment and endoscopes – A volumetric analysis. *Endoscopy* 2020; **52**: S11.

SUPPORTING INFORMATION

Additional supporting information can be found online in the Supporting Information section at the end of this article.

Video EYEBOSCO.mp4